

Scania ab recalls

Scania ab recalls

Reason for recall. Due to a deviation in the production process the wheel may crack and possibly fracture between the ventilation holes of the rim. How to check if the vehicle is recalled....

Due to a manufacturing defect, some track rods (between left and right wheel of the steered axle/s) were manufactured without the slots at the end of it. If the slot is missing, the clamping force of the clamp between the ball joint and the track rod will be low. This may result in a loss of vehicle control.

Scania Australia will contact all affected consumers. Consumers are advised to contact their Scania dealer or branch to make an appointment to have the repairs carried out, free of charge. For further information, owners should contact Scania Australia on 03 9217 3300 or via [https:// ...](https://...)

Recall Information. If there are any severe faults known on the vehicle it is presented here. When you have entered a chassis number into SWS you can click on the campaign button. This function demands that a unique vehicle is entered into the system. Recall Campaigns will be repaired at a Scania Dealer free of charge.

SCANIA RECALLS. Recall information for SCANIA Commercial Vehicles. Select the desired vehicle below to view all the recalls for that particular make & model. Please note - there could be multiple recalls for a specific model vehicle.

Go to your Scania market site for more information.

Enter a chassis number into SWS and you can find the technical specification regarding the specific vehicle including all certificates.

This information describes the vehicle as it left the factory, often without body but if the body was delivered from Scania factory the specification of the body will be included in this view.

Workshop procedures are published in SWS.

To learn more about workshop procedures, please read the SWS manual which is available in the Technical Information Shop.

The number one help to find electrical faults.

In the workshop manual you will find the traditional big sheets describing a part of the electrical system each.

Contact us for free full report



Scania ab recalls

Web: <https://www.kary.com.pl/contact-us/>

Email: energystorage2000@gmail.com

WhatsApp: 8613816583346

